

Do not dispose of this device in the trash along with other wastel According to the Law on Waste, electro coming from households free of charge and can any anount to up to that end point of collection, as well as to store the coasion of the purchase of new equipment (in accordance with the principle of other-new, regardless of brand). Electro thrown in the trash or abandoned in nature, pose a threat to the environment and human health.

Purpose

CE

Voltage indicator DMV-1T is devised to continuall measure the value of the voltage in a circuits of ONE-pahses.

Assembly

- 1. Take OFF the power.
- 2. Take off side grappleds of assembling indicator.
- 3. Put indicator in assembling hole.
- 4. Take on the assembling grappeleds and work to assembling frontage.
- 5. Power of multimeter connect to joints 1 and 2 with marks.
- 6. Voltage which is measure directly connect to joints 3 and 4 with marks.

- 1 -

D170313

Technical data

supply
range of reports
precision
display
power consumption
working temperature
dimensions
fixing
protection level

230V AC 0÷600V 1% 4×segment LED 14×8mm 3VA -5÷50°C 72×72×92mm 66×66mm IP20

Wiring diagram



- 2 -